



The following amounts of pyrites are to be imported in 1952:

<u>Producing Nation</u>	<u>Amount in Tons</u>
Bulgaria	30,000
Rumania	50,000
[REDACTED]	35,000

The balance of Czech needs is to be met by the Chvaletice and Brasy mines.

5. The following are lists of other imports for 1952

a) Sulphur:

<u>From</u>	<u>Amount</u>
[REDACTED]	5,000 tons
USSR [REDACTED]	5,000 tons
China [REDACTED]	5,000 tons

b) Powdered Sulphur:

<u>From</u>	<u>Amount</u>
[REDACTED]	3,000 tons

c) Graphite electrodes:

<u>From</u>	<u>Amount</u>
USSR [REDACTED]	1,000 tons
[REDACTED]	unknown quantity, under a 1951 contract

Czech industry requires 1,100 tons annually. By the end of the five Year Plan, 3,000 tons will be needed per year.

d) Carbon Electrodes:

<u>From</u>	<u>Amount</u>
Poland [REDACTED]	3,000 tons
[REDACTED]	smaller unspecified quantities

e) Phosphates:

<u>From</u>	<u>Amount</u>
USSR [REDACTED]	60,000 tons
[REDACTED]	90,000 tons

The capacity of the Czech chemical industry is about 300,000 tons a year, depending upon the production of sulphuric acid. About 150,000 tons are now produced.

f) Salt:

<u>From</u>	<u>Amount</u>
DDR	250,000 tons per year

Of this amount 180,000 tons are delivered to Nestenice for sodium (soda ash?) production and the rest is sent to Usti and Neratovice for salt electrolysis.

<u>From</u>	<u>Amount</u>
Poland	30,000 tons for Novaky and Brusov

g) Bones:

<u>From</u>	<u>Amount</u>
USSR	3,000 tons of poor quality

Czech engineers refused the shipment which included human bones, allegedly from mass graves.

6. Under the Czechoslovakian-Soviet trade agreement, the following chemicals are to be imported to Czechoslovakia:

<u>Chemical</u>	<u>Annual Amount in Tons</u>
Graphite electrodes	1,000
Chromites	6,000 to 8,000
Phosphorus	60,000 <del>to 8,000</del> kg?
Sulphur	5,000
Salt	180,000 to 200,000
Phenol	small quantity
Ilmenite	5,000

Czechoslovakia is to deliver a relatively small volume of drugs to the Soviet Union; the latter is reported not to want such drugs. Eight hundred tons of sulphuric carbon are also to be sent to the USSR.

SECRET